

	A	B	C
1	Northeast Community College- Wind Energy Required Tool List (2026)		
2	Tools Required First Day of Classes		
3	Estimated Cost: \$380		
4	Quantity	Description Program Required Tools	Part #
5	1	Screwdriver set - flat and Phillips	Wera - 05006604001
6	1 pair	Clear Safety Glasses	ANSI Z87.1 rated
7	1 pair	Fit leather work gloves (mechanics style)	
8	1 pair	Quality leather work boots with heel, shank support, composite safety toe – EH rated – oil resistant – slip resistant	A quality boot like: Timberland PRO Boondock 6 inch Composite Safety toe Waterproof Industrial Work Boot that has a heel stop, safety toe, and EH rated (see instructor)
9	2	Master Padlock non- conductive (for LOTO)	406 or 410 RED
10	1	Pocket sized notebook	
11	1	Headlamp for helmet	Energizer® Vision 300 Lumen Rechargeable headlamp
12	1	Precision Screwdriver set, 4 piece (flat and Phillips)	Greenlee 01530-03C
13	1	Wire stripper 7 1/8" 10-18 solid 12-20 stranded	Greenlee 1955-ss
14	1	Combination Lock for storage locker (Must be combination type)	